



Features:

- . Manual power on/off
- . Zero setting at any position
- . Metric/Inch system interchange at any position
- . With data output interface
- . Main scale jaw can be slid up and down to facilitate measurement of stepped sections

No.	Range mm/in	Resolution mm/in	H1 mm	H2 mm	H2 mm
117-101	150/ 6	0.01/.0005	110	40	37
117-102	200/ 8	0.01/.0005	120	50	40
117-103	300/12	0.01/.0005	130	60	42
117-105	500/20	0.01/.0005	210	100	69